<b>RTR Services Inc.</b>										RTR #: 41034								
PICK-UP TRUCK CONDITION REPORT			Ŧ	c					ACCOUNT NUMBER: ACCOUNT NAME:				95051 DMG Painting Services Inc.					
YEAR: 2024					IN:			EY6R12270					MILES: 11,579				IC.	
MAKE: Chevrolet						200411		STATE				TAGS:				YR:		
		Silverado 2			LICENSE: CAB TYPE:		Extended CC		-			10/10:40	TAGS.					
High Cours			n/						• DOOR: XTERIOR: White				INIER	IOR: Black/ Brown				
ENGINE: V-8 6.6 L															DATI	TING -35		
TRANS: Automatic				FUEL: GAS														
DOES MOTOR RUN? 🛛 YES 🗌 NO 🛛 CAN IT BE DRIVEN? 🖾 YES 📄 NO 🔹 COLLISION DAMAGE? 📄 YES 📄 PHYSICAL APPEARANCE														<b>&gt;</b>   \2	J NO			
			GD	FR PR N/A			COMM								OPTIONS			
	FRONT BUMPER			$\boxtimes$			Scratch								PWR ST			
	HEAD LIGHTS			$\boxtimes$											PWR BF		i	
	HOOD TURN SIGNALS GRILL			$\boxtimes$											PWR LC	-	19	
ВОDҮ															PWR SE			
	D FRONT FENDER D DOOR D REAR FENDER			$\boxtimes$											LEATHE	-	-	
				$\boxtimes$											PWR MI CRUISE			
	CARGO BED			$\boxtimes$											TILT WH		NOL	
	REAR BUMPER														TINTED		-	
	TAIL LIGHTS TAIL GATE			$\boxtimes$											AIR CON			
	TAIL PIPE			$\boxtimes$											SUN RO			
	P FRONT FENDER P DOOR			$\boxtimes$											AM FM I			
	P DOOR P REAR FENDER																	
	ТОР			$\boxtimes$											CUSTO	N WHE	ELS	
	D FRONT D REAR			$\boxtimes$				T275/65R2 T275/65R2							4 X 4 TOW PA	CKAC	`E	
RES	P FRONT							T275/65R2							Bluetoo			
TIRI	P REAR			$\boxtimes$			75 % L	T275/65R2	) SIZE:					$\square$	Back-Up	Cam	era	
	SPARE WINDSHIELD			$\boxtimes$			75 % L	T275/65R2	) SIZE:									
6	D FRONT DOOR			$\square$														
LASS	D REAR PANEL			$\boxtimes$														
				$\boxtimes$														
	REAR WINDOW			$\boxtimes$														
ĸ	DASH DOOR PANELS			Ø														
DOOR B B B B B B B B B B B B B B B B B B		INELS		$\boxtimes$														
INTE	CARPET			$\square$														
	HEADLIN	ER	GD	FR	PR		N/A	COMMENT	S'									
	ENGINE			$\boxtimes$					•.									
CAL		TRANSMISSION																
MECHANICAL	CLUTCH BRAKES			$\square$														
Ы	FRONT END			$\boxtimes$														
ME	REAR END BATTERY/ELECTR			$\boxtimes$														
COMMENTS: Miliage Unverified.																		
		<b>J</b>																

11/29/24

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.

RTR Services Inc. • 2747 Pence Loop SE Salem OR 97302 • 1.800.238.3294 • FAX 503.399.0421 The information contained within this report is private and confidential. It is solely intended for the use of RTR Services Inc. and its client. Any unauthorized use and or reproduction is prohibited. 107




ACCOUNT NUMBER 95051



VIN:2GC4YREY6R1227059












12/2/2024 1 OF 6



ACCOUNT NUMBER 95051
















12/2/2024 2 OF 6



## ACCOUNT NUMBER 95051















12/2/2024 3 OF 6




ACCOUNT NUMBER 95051















12/2/2024 4 OF 6




ACCOUNT NUMBER 95051













## PHOTO SHEET

DMG Painting Services Inc.

## ACCOUNT NUMBER 95051

